

LEAD SERVICE LINE VERIFICATION AND REPLACEMENT PROGRAM FOR
RICEVILLE UTILITY DISTRICT

LEAD AND COPPER ON UTILITY SIDE OF THE METER:

RICEVILLE UTILITY DISTRICT **has not** found any Lead or Galvanized service lines in our system (from main to meter). This will continue to be monitored and reported.

LEAD AND COPPER ON UTILITY SIDE OF THE METER:

EPA Lead and Copper inventory list was issued to all Utilities requiring all served locations to be placed on a master list that is available to all customers at www.ricevilleutilitydistrict.org or upon request at our office at 3802 Highway 11S Riceville TN 37370.

Customers that reported having Lead, Galvanized needing replacement or Unknown on their side of the meter, with plumbing installed before 1988, have been notified by mail and is asked to either update our information if this is incorrect or to work toward replacing the lines within the next 10 years.

At this time no sampling is required but if concerned please request to be added to our Triennial Lead and Copper Sampling site list. (qualifications apply)

EPA LCRI has not issued any more requirements or suggestions for financial help in replacing or monitoring the sites listed on our Potential Lead Exposure Risk List (available in the office upon request) but Riceville Utility District will continue to monitor the LCRI and will update our program accordingly.

Customer notification can be located our website at www.ricevilleutilitydistrict.org or mailed directly to the customer if the customer is listed on our Potential lead Exposure Risk list.

INVENTORY:

Monitored and updated daily.

COMMUNICATION:

Location in our system with service lines before 1988 found to have Lead, Galvanized needing replacing or Unknown will automatically require the customer be notified and be placed on our Potential Lead Exposure Risk List.